W	ork	Orde	r ID	53850	١
* *	UI K	VIUC		しんいいんり	,

November 19, 2009 3:03:36 PM

Page 1

									·	
Item ID:	D3579-046		Accept				S	etup St	art	
Revision ID:	С							C.		
Item Name:	Shoulder Harness	d.						St	op	
Start Date:	11/19/09 Start Qty: 1.00			Cust Item I	D:					
Required Date:	: 11/26/09 Req'd Qty: 1.00			Customer:						
Reference:	Return 2009 / RA109076									
Approvals:	Process Plan:	Date:	Tooling: SPC (Y/N):	Date:			F	Run St		
	QC:	Date: 05-11-15		Date:			Stop			
Sequence ID/ Work Center I	Operation Description		Set Up/ Run Hours	Draw Number	Draw Rev.	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr	Revision Nbr						-			
D3579	Rev C									
100	QC5- Inspect part cor	mpleteness to step on W/O	0.00							
		1						1		65.11.15
QC	Memo		0.00				·			- - 0) (()
Quality Control	Orignal I NCR09-0	332561. Buckles are scrap.								,
110			0.00				- ()	·		
Purchasing	Memo	ļ	0.00				CX	09/13	2/01	
Purchasing		supplier (Schroth) per NCR	09-074.							
120	QC21- Final Inspection	on - Work Order Release	0.00				•	0 \		
QC	Memo		0.00				/	10.01	<u> </u>	
Quality Control										

W 32.224